

08/1984 TOYOTA CELICA (MA61L-BLMQFW)


SPR EUR EUG LB LHD 5MGE TWC MTM 5F

47-05: FRONT DISC BRAKE CALIPER & DUST COVER


('8108-) — ILLUSTR. NO. 2 OF 2

CAUTION
 THE COMPONENT PARTS FOR PNC'S 04465, 04945 AND 04947 DO NOT ALWAYS MATCH THESE ILLUSTRATIONS. (EX. SHAPE, QUANTITIES, ETC.) BECAUSE THESE ILLUSTRATIONS ARE USED IN COMMON.


04465



04945



04947



- 04465** **PAD KIT, DISC BRAKE, FRONT (PAD ONLY)**
- 04465-14200 MA61..EUR, ME
- 04945** **SHIM KIT, ANTI SQUEAL, FRONT**
- 04945-14060 MA61..EUR, ME
- 04947** **FITTING KIT, DISC BRAKE, FRONT**
- 04947-14240 MA61..EUR, ME

1 € 74.51
 1 € 5.25
 1 € 33.86

Toyota Recall Information Toyota.com/Recall
 Get Updated Info & Read Important Messages on Toyota Recall Topics.

BRAKE JOB \$69.95 www.AutomotiveRepairGroup.com
 Includes Parts & Labor!* Lowest prices in VA, DC & MD

Russel Toyota www.RusselToyota.com
 Compare our Internet Specials Huge Discounts, Save Thousands

Quick. Easy. Trusted. viodealer.com/DV0002
 Now OPEN in Fairfax City \$19.99 Full Service Oil Change

Ads by Google

08/1984 TOYOTA CELICA (MA61L-BLMQFW)

SPR EUR EUG LB LHD 5MGE TWC MTM 5F


47-07: REAR DISC BRAKE CALIPER & DUST COVER

('8108-)AA63,MA61,RA63..GT,SPR — ILLUSTR NO. 2 OF 2


CAUTION

THE COMPONENT PARTS FOR PNC'S 04466, 04946 AND 04948 DO NOT ALWAYS MATCH THESE ILLUSTRATIONS. (EX. SHAPE, QUANTITIES, ETC.) BECAUSE THESE ILLUSTRATIONS ARE USED IN COMMON.


04466



04946



04948



| | | |
|--------------|--|-----------|
| 04466 | PAD KIT, DISC BRAKE, REAR (PAD ONLY) | |
| 04466-14130 | AA63, RA63, MA61..GT, SPR | 1 € 33.84 |
| 04946 | SHIM KIT, ANTI SQUEAL (FOR REAR DISC BRAKE) | |
| 04946-14060 | AA63, RA63, MA61..GT, SPR | 1 € 5.25 |
| 04948 | FITTING KIT, DISC BRAKE, REAR | |
| 04948-14060 | AA63, RA63, MA61..GT, SPR | 1 € 27.87 |